


Initial configuration of
the machine at the exit
of our workshops

STM 75 NIBBI N1

Figure N°1



REVISED
On : 02-06-2020

REVISION : B



**DAIRON
S.A.S**

Since 1958

DAIRON S.A.S. D92 Les Hunaudières
72230 MULSANNE
☎ 02 43 422 422 Fax. 02 43 422 000
E-mail. Rotadairon@wanadoo.fr

REV : B	PART LIST FIGURE N°1 STM 75 NIBBI N1 FROM B248		02/06/2020
ITEM	DESCRIPTION	PARTS REFERENCES	
		STM 75 NIBBI N1	QTY
1	SMALL PLATE	630-1013	1
2	HH SCREW M 12 - 30	850-1046	3
	HEX NUT M 12	260-1012	3
3	RIGHT SIDE	5072-195-1033	1
4	BEARING 6206	690-1018	1
5	CIRCLIP Ø 30 EXT.	190-1002	1
6	CIRCLIP Ø 62 INT	190-1016	1
7	SHIM WASHER	695-1114	1
8	HIDE DUST RIGHT SIDE	161-1001	1
9	COUPLING SLEEVE (NIBBI)	5070-240-1033	1
10	PARALLEL KEY 8 x 7 x 35	192-1002	1
11	TRANSFER CASE	095-1046	1
12	SHAFT TUBE	094-1015	1
13	BEARING 6007	690-1025	1
14	CIRCLIP Ø 35 EXT	190-1009	1
15	O-RING	400-1010	1
16	LIP SEAL 35 X 62 X 10	400-1018	1
17	SCREW-IN SHAFT TUBE HOUSING	160-1007	1
18	PAPER GASKET	415-1016	1
19	HH SCREW M 10-35	850-1022	6
	HEX NUT M 10	260-1011	6
20	CHAIN SPROCKET 11T - 25,4 PITCH	600-1010	1
21	CIRCLIP Ø 35 EXT	190-1009	1
22	CHAIN TENSIONER	5075-730-1002	1
23	CIRCLIP Ø 35 EXT	190-1009	1
24	SLEEVE OF TENSIONER	240-1020	1
25	WASHER OF TENSIONER	695-1057	1
26	HH SCREW M 12-60	850-2009	1
	HEX NUT M 12	260-1012	1
27	CORK SEAL	420-1009	1
28	HH SCREW M 16-80	850-2011	1
	HEX NUT M 16	260-1015	1
29	CHAIN CASE CAP	155-1002	1
30	COPPER SEAL	410-1001	1
31	DRAIN CAP	155-1016	1

REV : B	PART LIST FIGURE N°1 STM 75 NIBBI N1 FROM B248		02/06/2020
ITEM	DESCRIPTION	PARTS REFERENCES	
		STM 75 NIBBI N1	QTY
32	HH SCREW M 8-25	850-2024	12
	HEX NUT M 8	260-1010	12
33	CHAIN CASE	180-1014	1
34	HH SCREW M 16-50	850-1016	1
35	SHOCK ABSORBER MOUNTING	145-1003	1
36	BELLEVILLE WASHER	695-1092	1
37	FRONT CLUTCH PLATE	5075-250-1011	1
38	CHAIN 42 LINKS - 25,4 PITCH	175-1012	1
39	CHAIN SPROCKET	5055-600-1039	1
40	CIRCLIP Ø 40 EXT.	190-1001	1
41	REAR CLUTCH PLATE	5075-250-1010	1
42	CIRCLIP Ø 80 INT	190-1008	1
43	BEARING 6208	690-1004	1
44	RIGHT SIDE	195-1132	1
45	HH SCREW M 10 -25	850-2003	5
	HEX NUT M 10	260-1011	5
46	CIRCLIP Ø 62 INT	190-1016	1
47	SECONDARY SHAFT	5055-100-1069	1
48	HSHC SCREW S/S A2 8 * 20 Din 912	850-4006	4
49	O-RING SEAL Ø 56 X 3	400-1067	1
50	PAPER GASKET	415-1014	1
51	BEARING HOUSING	160-1030	1
52	CASSETTE SEAL TYPE 3 Ø45 X Ø70 X 14.5/17	400-1044	1
53	HH SCREW 1/2 - 43	850-1003	6
	HEAVY HEX NUT 1/2	260-1002	6
54	DRIVE PLATE	630-1118	1
55	BLADE BOLT	4000-001	32
56	RIGHT BLADE	450-1001	8
57	ROTOR	5075-760-1014	1
58	LEFT BLADE	450-1002	8

Initial configuration of
the machine at the exit
of our workshops


REVISED

On : 02-06-2020

REVISION : B

STM 75 NIBBI N1


Figure N°2



REV : B	PART LIST FIGURE N°2 STM 75 NIBBI N1 FROM B248		02/06/2020
ITEM	DESCRIPTION	PARTS REFERENCES	
		STM 75 NIBBI N1	QTY
1	HOOD	5072-770-1657	1
2	HH SCREW M 10 -45	850-2008	1
	HEX NUT M 10	260-1011	1
3	SHOE	5055-710-1007	1
4	HH SCREW M 10-50	850-2077	1
	HEX NUT M 10	260-1011	1
5	HH SCREW M 12-60	850-2009	1
	HEX NUT M 12	260-1014	1
	HEX NUT M 12	260-1012	1
6	SPRING	660-1005	1
7	HH SCREW M 10 -25	850-2003	5
	HEX NUT M 10	260-1011	5
8	RIGHT SIDE	195-1132	1
9	HEX WASHER HEAD SCREW S/S A2 6 * 20	850-4003	8
10	SHEET OF FIXING BIB	770-1235	1
11	BIB	645-1008	1
12	MACHINE DATA PLATE	460-1010	1
13	RIVET Ø3 X 10	697-1002	4
14	DECAL - READ THE INSTRUCTION MANUAL	460-1006	1
15	DECAL - DO NOT CLIMB ON MACHINE	460-1009	1
16	PLASTIC CAP 30 x 30	156-1020	1
17	TRANSFER CASE	095-1046	1
18	HH SCREW M 10-20 YZP	850-2063	4
	WASHER W 10	695-1014	4
	WASHER MU 10 YZP	695-1017	4
19	HH SCREW M 10-80 YZP	850-2062	2
	WASHER MU 10 YZP	695-1017	4
	HEX NUT M 10	260-1011	2
20	HITCH	5070-640-1739	1
21	HH SCREW M 10-20 YZP	850-2063	4
	WASHER W 10	695-1014	4
	WASHER MU 10 YZP	695-1017	4
22	HANDLE	610-1036	1
23	CRUTCH	5072-750-1655	1

REV : B	PART LIST FIGURE N°2 STM 75 NIBBI N1 FROM B248		02/06/2020
ITEM	DESCRIPTION	PARTS REFERENCES	
		STM 75 NIBBI N1	QTY
24	HEX WASHER HEAD SCREW S/S A2 6 * 20	850-4003	2
	NUT S/S A2 M6 DIN 985	260-4009	2
25	INSTRUCTION MANUAL BOX	180-1032	1
26	DECAL - DO NOT STAND UNDER THE LOAD	460-1005	1
27	HS HC SCREW M 10-130	850-3046	2
	HEX NUT M 10	260-1011	2
28	HH SCREW M 10 -25	850-2003	6
	HEX NUT M 10	260-1011	6
29	RIGHT SIDE	5072-195-1033	1
30	DECAL - FEET / HAND SEVERING HAZARDS	460-1007	1
31	HS HC SCREW M 8 - 30	850-3020	23
	HEX NUT M 8	260-1010	23
32	GRID CLAMP	150-1002	6
33	GRID	5070-770-1082	1
34	GRID FINGER	210-1004	24

Initial configuration of
the machine at the exit
of our workshops



STM 75 NIBBI N1

Figure N°3

REVISED

On : 02-06-2020

REVISION : B



**DAIRON
S.A.S**

Since 1958

DAIRON S.A.S. D92 Les Hunaudières
72230 MULSANNE

☎ 02 43 422 422 Fax. 02 43 422 000
E-mail. Rotadairon@wanadoo.fr

REV : B	PART LIST FIGURE N°3 STM 75 NIBBI N1 FROM B248		02/06/2020
ITEM	DESCRIPTION	PARTS REFERENCES	
		STM 75 NIBBI N1	QTY
1	HH SCREW M 16-80	850-2011	1
	HEX NUT M 16	260-1008	1
2	SETTING SYSTEM CHASSIS	5072-685-1023	1
3	HH SCREW M 16-90	850-2081	1
	HEX NUT M 16	260-1008	1
4	HH SCREW M 12-30	850-2016	2
	HEX NUT M 12	260-1012	2
5	WASHER Ø13 / Ø42 / 4	695-1027	2
6	SPACING WASHER	695-1109	2
7	ROLLER FRAME	5072-270-1323	1
8	CAST IRON BEARING HOUSING UCFL 204	690-1040	2
9	HH SCREW M 10 - 30	850-2002	4
	HEX NUT M 10	260-1011	4
10	MD ROLLER	5072-505-1022	1
11	DECAL - CATCHING HAZARD	460-1012	2
12	SCRAPER	770-1232	1
13	HH SCREW M 10 -25	850-2003	4
	WASHER MU 10 YZP	695-1017	4
	HEX NUT M 10	260-1011	4
14	PLASTIC CAP 40 x 40	156-1017	2
15	LEVELLING BLADE	450-1067	1